CONFIDENTIAL

MG/198

SERVICE MEMORANDUM

SUBJECT:

3rd Jan 1957

IMPORTANT MODIFICATIONS

Parts List Amendment No.

Cylinder head - heater outlet

From Engine No.12723 - MGA

1753 - magnette ("ZB")

Nil (No change in rart No

To reduce restriction in flow from head to heater outle pipe

Diameter of outlet increased from .5" to 625 (12.8 to 15.87 mm).

Wheel cylinder Banjo connection - rear brakes

Wheel cylinder - From Car No. 22741 - MGA

PMG/222

Improved design

90° banjo connection replaces straight type.

Earlier cars can be modified.