MG/286

SERVICE MEMORANDUM

10 November 1959

IMPORTANT MODIFICATIONS

Parts List

Amendment No.

Buffer -

From Car No. 4451 - Magnette (Mark III)

PMG/390

bonnet panel

To prevent damage to bonnet and

radiator grille flange

Two rubber buffers fitted to front

of bonnet panel.

Earlier cars may be modified.

Steering wheel

From Car No. 4846 - Magnette (Mark III)

PMG/394

To promote quicker flashing indicator

cancellation

Steering wheel flashing indicator lugs

modified.

Interchangeable.

Brak**e**

From Car No. 5795 - RHD - Magnette (Mark III)

PMG/398

master cylinder

Improved design

Modified master cylinder introduced having

additional taper seal in piston.

Interchangeable.

Air cleaner From Car No. 2468 - 'MGA' Twin Cam

PMG/394

Improved design

Venturi incorporated in air cleaner

Air cleaners interchangeable.